

Mercedes Sprinter 518 2.9CDI 180HP 2007

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

