

BMW X5 3.0td 218HP 2005

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

