

Chrysler 300C 3.0CRD 218HP 2005

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

