

## Mercedes A170 CDI 90HP 2003

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

