

## Mitsubishi Carisma 1.9Di-D 115HP 2003

1. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

